Approved For Release 2002/05/17 GIA-RDP78B04747A000600080035-0

6 July 1961

	MEMORANDUM FOR THE RECORD	
	SUBJECT: Telephone Conversation withonon	25X1A
25X1A	1. Machine one, or prototype has been consistently giving trouble insofar as spurious intermittent electrical signals are concerned. This trouble has been occurring since the first week in May when the undersigned last inspected the equipment. The first tests since that time are being run this date and, if successful, will be sent to us. In addition to internal spurious signals, trouble has been experienced with the new tape reader generating signals which trigger transistorized controls. The tape reader was returned to original manufacturer twice for clear up without successfinally reworked the reader themselves and have apparently been successful, for the tests are set with number one this week. It will be torn down, rebuilt and will be the fourth rectifier to be delivered.	
	2. Rectifier two should be ready for testing at about the second week in August with delivery approximately 15 September 1961. No further delivery schedules on three, four, or reworked one have been firmed.	25X1A
25X1A	is taking into consideration the screen room brochure which we sent them and will submit to us within a week their recommendations as to which screen room would be best suited for use with our rectifier. In all probability the screen room chosen will have solid copper walls and, therefore, can serve as the dark room as well as the screen room.	25X1A
25X1A	Declass Review by NIMA/DOD	

SEGRET

STATINTL Bestifiers! - 1. Sereen room - en the right one. - rud in a wedon 2. Notice, # 2? - (will have by eng week) STATINTL where ?-was STATINTL